

SDMS US EPA REGION V -1

**SOME IMAGES WITHIN THIS
DOCUMENT MAY BE ILLEGIBLE
DUE TO BAD SOURCE
DOCUMENTS.**

157747

Date: February 4, 1987

Time: 10:00 (A.M.)

Photograph By:

R.L. Johnson

Location: LPC- 1630450030

St. Clair Co.

East St. Louis / U.S.D.

Comments: Photograph taken

toward the North

TANKER UNLOADING OPERATION

651-1



Date: _____

Time: _____ A.M. P.M.

Photograph By:

Location: LPC-

Co.

Comments: Photograph taken

toward the

RECEIVED

FEB 10 1987

EPA-DLPC

Date: February 4, 1987

Time: 2:10 P.M. A.M.

Photograph By:

R. L. Johnson

Location: LPC- 1631210014

St. Clair Co.

Sauget/Moss American

Comments: Photograph taken

toward the North

SAMPLE X201 IS WHITE MAT'L

651-2 ON LEFT OF PHOTO



Date: _____

Time: _____ A.M. P.M.

Photograph By:

Location: LPC- _____

Co. _____

Comments: Photograph taken

toward the _____

RECEIVED

FEB 10 1987

IEPA-DLPC

Date: February 4, 1987

Time: 2:17 A.M. P.M.

Photograph By:

R. L. Johnson

Location: LPC-1631210014

St. Clair Co.

Sauget/Moss American

Comments: Photograph taken

toward the North

FORMER BOILER ROOM AREA -

651-3 CURRENT CONDITIONS

Date: February 4, 1987

Time: 2:17 A.M. P.M.

Photograph By:

R. L. Johnson

Location: LPC-1631210014


St. Clair Co.

Sauget/Moss American

Comments: Photograph taken

toward the North

651-4



Date: February 4, 1987

Time: 2:20 A.M. P.M.

Photograph By:

Location: LPC- 1631210014

St. Clair Co.

Sauget/Moss American

Comments: Photograph taken

toward the East

651-5 SAMPLE X203



Date: February 4, 1987

Time: 2:25 P.M. A.M.

Photograph By:

Location: LPC- 1631210014

St. Clair Co.

Sauget/Moss American

Comments: Photograph taken

toward the East

SAMPLE X202

651-6



Date: February 4, 1987

Time: 3:00 A.M. P.M.

Photograph By:

R L Johnson

Location: LPC- 1630050009

St. Clair Co.

Alorton/Owens-Rhodes

Comments: Photograph taken

toward the Southeast

SITE CONDITIONS -

651-7 SMOLDERING FIRE

Date: February 4, 1987

Time: 3:00 A.M. P.M.

Photograph By:

R L Johnson

Location: LPC- 1630050009

St. Clair Co.

Alorton/Owens-Rhodes

Comments: Photograph taken

toward the Southeast

PANORAMIC w/ 651-7

651-8



Date: February 4, 1987

Time: 3:05 A.M. (P.M.)

Photograph By:

RL Johnson

Location: LPC-1630050009

St. Clair Co.

Alorton/Owens-Rhodes

Comments: Photograph taken

toward the South

SITE CONDITION

651-9 PHOTOS TAKEN STANDING
ON BAUKITE TAILINGS DIKE
("RED MUD")

Date: February 4, 1987

Time: 3:05 A.M. (P.M.)

Photograph By:

RL Johnson

Location: LPC-1630050009

St. Clair Co.


Alorton/Owens-Rhodes

Comments: Photograph taken

toward the South

PANORAMIC w/651-9411

651-10



Date: February 4, 1987

Time: 3:05 (P.M.) A.M. (P.M.)

Photograph By:

R L Johnson

Location: LPC- 1630050009

St. Clair Co.

Alorton/Owens-Rhodes

Comments: Photograph taken

toward the South

PANORAMIC w/ 651-9110

651-11

Date: _____

Time: _____ A.M. P.M.

Photograph By:

Location: LPC-

Co.

/

Comments: Photograph taken

toward the

Date: February 4, 1987

Time: 3:07 A.M. P.M.

Photograph By:

R L Johnson

Location: LPC-1630050009

St. Clair Co.

Alorton/Owens-Rhodes

Comments: Photograph taken

toward the South

SITE CONDITIONS - FASTSIDE

651-12

Date: February 4, 1987

Time: 3:07 A.M. P.M.

Photograph By:

R L Johnson

Location: LPC-1630050009

St. Clair Co.

Alorton/Owens-Rhodes

Comments: Photograph taken

toward the South

SITE COND

651-13 PANORAMIC w/ 651-12

